

Method card

BUZIL-WERK Wagner GmbH & Co. KG

INDUMASTER® PROTECT IR 30

Application area:
Industrial surface



pH 10

<p>Dilution</p>	<p>100 - 200 ml / 10 l water 200 - 500 ml / 10 l water</p>	 	
<p>Suitable for</p>	<p>Machine cleaning; Workshops; Industry</p>	<p>Not suitable for</p>	<p>Textile surfaces; Acrylic glass</p>
<p>Application</p>	<p>Alkali-resistant materials, surfaces and floor coverings; Production machines (CNC); Truck tarpaulins; Tarpaulins</p>		
<p> Trouble Shooting</p> <p>Before initial use: Test material compatibility!</p>	<p>Issue / Failure / Requirement</p> <ul style="list-style-type: none"> ▪ Leaves streaks / film on surface / too much foam in dilution ▪ Low / weak cleaning effect ▪ No cleaning effect ▪ Damage on surface (discoloration, material swelling, etc.) ▪ Grey / mat appearance of surface due to hard water 	<p>Solving Issue</p> <ul style="list-style-type: none"> ▪ Adjust product dilution ▪ Select industrial cleaner i.e. Indumaster® Universal IR 55 ▪ Select problem solver i.e. Indumaster® Forte IR 42 ▪ Check material's chemical and water resistance ▪ Clean periodically with O Tens Azid G 501 	

Method card

BUZIL-WERK Wagner GmbH & Co. KG

ALTERNATIVE PRODUCT | INDUMASTER® PROTECT IR 30

Application area:
Industrial surface



pH 10

Alternative Product	Differentiation	Application
Indumaster® Step IR 16	Industrial cleaner with no corrosion protection	Industrial cleaning
Indumaster® Universal IR 55	Ecological industrial cleaner with no corrosion protection	Industrial cleaning